


# OE bare local supports

---

## 🐾 Missing



- 🐾 Bus tapes
- 🐾 EoS cards (part of bus tape?)
- 🐾 MOPS (part of EoS)

## [IS.3.2] Inner System - Loaded Local Supports



# IS supports

- 🐾 Modules in carrier (from everywhere)
  - 🐾 Visual inspection, basic el tests
- 🐾 1/2 ring (from Manchester)
  - 🐾 Visual inspection, QC test of bus tapes, MOPS?
- 🐾 Power pigtail (from Genoa, Ettore)
  - 🐾 Should have been done in Genoa
- 🐾 Data type-0 cables??? Ask Jo



# OE supports

- Can transport box be flushed with nitrogen
- Module loading (loading plus soldering of pigtails)
  - Glue batch number to be provided per module
- QC (metrology)
  - Metrology: Glue thickness per module, module position, image
  - Check for shorts (from soldering). Now yet clear how to
  - Electrical test
    - Same testing as during reception but now under serial powering
    - Basic scans, sensor IV, noise scan, cross-talk scan, bump bond quality,
    - Tuning?

